



Design  
Build  
Products  
Nursery

## Ramsden Bellhouse

A series of potentially dangerous deep-seated failures on a railway embankment required treatment to prevent further slips.



The geotechnical issues of ground stability were resolved using soil nailing. The surface erosion was solved by using VMax C350. C350 is a composite Turf Reinforcement Mat (TRM) and was installed over prepared seeded topsoil.

The whole surface was then covered with rock netting.

The C350 is a permanent solution that will offer long term erosion control and vegetative reinforcement.

[www.salixrw.com](http://www.salixrw.com)  
Email: [info@salixrw.com](mailto:info@salixrw.com)  
Tel: 0330 002 1788

# Salix